

Paul A. Braddick Owner/Pilot WBDroneServices@Outlook.com



346-616-4312 1309 Carolyn Ct. Humble,TX. 77338



#### Inspection: 1309 Carolyn Ct Humble TX 77338

Report date: Apr 21, 2020

Annotations: 13

Report Images: 1

> Status: Draft

> > Type: Roof

Company: Paul braddick

Report created by: Paul braddick sgtbraddick@gmail.com



#### Severity overview

Severity 1	Severity 2	Severity 3	Severity 4	Severity 5	POI ( ? )
2	0	2	9	0	0

1309 Carolyn Ct Humble TX 77338 - Summary

# Annotation overview


Id	Severity	lssues	Comments	Page
1035710	3	damaged vent	damage from animals chewing plastic vent sides	4
1035711	1	Worn section		4
1035712	3	damaged vent	damage from animals chewing through plastic vent sides	5
1035713	4	Worn section	shingles broken and worn from weather	5
1035719	4	Worn section		5
1035720	4	Worn section		5
1035721	4	Worn section		5
1035722	4	Worn section		6
1035723	4	Worn section		6
1035724	4	Worn section		6
1035725	4	Worn section		6
1035726	4	Worn section		6
1035728	1	Worn section	damage from roofing crew	7

### 1309 Carolyn Ct Humble TX 77338

File name:	IMG_0358.JPG	Altitude:	22.4m
Date taken:	Apr 6, 2020 3:52:50 PM	Heading:	East (84.100006°)
Position:	29.9898694,-95.2551250	User tags:	No tags available



For a more detailed overview go to cloud.connexicore.com/#/inspection/12730?image=4534825





# 1035712 Severity: 3 damaged vent

Premedy action: replace vent

Paul braddick: damage from animals chewing through plastic vent sides




1035713 Severity: 4 Worn section

**Remedy action:** replace

Paul braddick: shingles broken and worn from weather



1035719 Severity: 4 Worn section



1035720 Severity: 4 Worn section



1035721 Severity: 4 Worn section

1035722 Severity: 4 Worn section
1035723 Severity: 4 Worn section
1035724 Severity: 4 Worn section
1035725 Severity: 4 Worn section
1035726 Severity: 4 Worn section



1035728 Severity: 1 Worn section

P Remedy action: replace

Paul braddick: damage from roofing crew